

MOD/206/006 issue 1

LAA CLASSIFICATION: A

LAA Approval:



Date: 16.4.08

AIRWORTHINESS INFORMATION LEAFLET



CFM STREAK AND STARSTREAK INCORPORATION OF CFM SERVICE BULLETIN No. 9 – FRONT HANGER BRACKET SUPPORT

Applicability:

All Shadow Variants.

Compliance by:

Within 5 flying hours from the issue date of this bulletin.

Background:

The recent failure of an F153 front hanger tube bracket on a CFM Streak Shadow has highlighted the need for constant vigilance in this area of the Shadow's airframe. This Airworthiness Information Leaflet (AIL) requires that owners or operators ensure that the plywood bracket support, recommended by CFM Metal-Fax, is fitted.

Actions Required:

Inspect aircraft and ensure plywood support is fitted; if fitted, no further action is required. If the plywood bracket support is not fitted then a bracket needs to be constructed and fitted as per CFM Metal-Fax Service Bulletin No.9 which is reproduced in full on the reverse of this AIL. Drawings and/or parts for this bracket support are available from the Shadow Service centre (see address below).

Certification:

1. A/C with bracket support: No further action.
2. A/C without support fitted: After fitment Inspection by LAA inspector required.

Logbook entry required stating that LAA/MOD/206/006 has been complied with.

Shadow assistance and advice
can be obtained from:
Shadow Flight Centre,
Hanger 3,
Old Sarum Airfield,
Salisbury,
Wiltshire.
SP4 6BJ
Tel: 01722 410576

Classification: A – An inspection or modification considered mandatory by the LAA
Classification: B – An inspection or modification recommended by the LAA
Classification: C – Material published for information and guidance