



**United Kingdom
Civil Aviation Authority**

MPD No: 2003-004

Issue Date: 30 April 2003

MANDATORY PERMIT DIRECTIVE

The following action required by this Mandatory Permit Directive (MPD) is mandatory for applicable aircraft registered in the United Kingdom operating on a UK CAA Permit to Fly.

MPD: 2003-004 CFM

Subject: Installation of ASI and altimeter correction placards.

Applicability: CFM Shadow Series B and BD aeroplanes.

Reason: Investigations undertaken by the BMAA have shown that due to the location of the static pressure source on this aeroplane type, the ASI and altimeter over-read significantly. This MPD requires placards to be fitted and an operators manual supplement to be added to indicate the necessary corrections.

Compliance: Before 1 June 2003 or at the next permit renewal, whichever is the sooner, install the correction placards in accordance with British Microlight Aircraft Association (BMAA) Service Bulletin 1681 issue 1.

A copy of BMAA Service Bulletin 1681 and further information can be obtained from:

British Microlight Aircraft Association
Bullring
Deddington
Banbury
Oxon
OX15 0TT

Tel: 01869 338888
Fax: 01869 337116
Email: cto@bmaa.org

Record compliance with this MPD in the aircraft log book.

This MPD becomes effective on 3 May 2003.