

SERVICE BULLETINNO. 1DATE 1.3.85CFM METAL-FAX LTD CONSIDERSCOMPLIANCE - ~~Mandatory~~/Recommended/~~Optional~~
(delete which is not applicable)

<u>SUBJECT</u>	UNDERCARRIAGE FIBRE GLASS PULTRUSION ROD - 1" DIA.
<u>MODELS AFFECTED</u>	SHADOW SERIES B
<u>SERIES NOS. AFFECTED</u>	003, 004, 005, 006, 007.
<u>COMPLIANCE TIME</u>	AT YOUR CONVENIENCE
<u>PURPOSE</u>	TO REPLACE UNDERCARRIAGE FIBRE GLASS RODS, BOTH SIDES, WITH NEW MATERIAL.
<u>INSTRUCTIONS</u>	INSPECT BOTH RODS AT TOP AND BOTTOM ENDS ON EITHER SIDE FOR SIGNS OF DETERIORATION. DO NOT PLACE LOADS IN REAR COCKPIT UNTIL NEW RODS HAVE BEEN FITTED.
<u>MATERIAL REQUIRED</u>	AS SUPPLIED BY CFM METAL-FAX - TO INCLUDE ARALDITE.
<u>AVAILABILITY OF PARTS</u>	SUPPLIED FREE OF CHARGE AS SOON AS POSSIBLE.
<u>EFFECTIVITY DATE</u>	IMMEDIATE
<u>SUMMARY</u>	THERE HAS BEEN A FAILURE ON A/C SERIAL NO. 005 AT THE TOP END OF THE STBD GLASS FIBRE ROD, DUE TO THE SUPPLY OF SUB-STANDARD MATERIAL.
<u>NOTES</u>	DETAILED FITTING INSTRUCTIONS WILL BE SENT WITH NEW MATERIAL.