MPD No: 1995-082

MANDATORY PERMIT DIRECTIVE

The following action required by this Mandatory Permit Directive (MPD) is mandatory for applicable aircraft registered in the United Kingdom operating on a UK CAA Permit to Fly.

MPD: 1995-082 CFM METAL-FAX

Subject: Air intake muffler and propeller pitch change.

Applicability: CFM Metal-Fax Shadow Series B and Shadow Series B-D microlights Serial Nos KO16, KO18, KO20, KO21, KO22, KO23, KO27, 024, 026, 028 and 029.

Reason: To conform to the Noise Certification requirements introduced on 1 April 1986. This MPD is raised to record the mandatory requirement shown in Type Approval Data Sheets Nos BM-6 Issue 3 and BM-19 Issue 2.

Compliance: Before the 1 April 1986 embody Mod 008 which requires the replacement of the foam air filter with a Rotax intake muffler, the carburettor main jet changed to No 155 and the Newton propeller changed in accordance with CFM Metal – Fax Service Bulletin No 2.

This MPD becomes effective on 29 December 1995.

Enquiries regarding this MPD should be made to the United Kingdom Civil Aviation Authority, Aircraft Maintenance Approvals Section, Safety Regulation Group, Aviation House, Gatwick Airport South, West Sussex RH6 0YR. Telephone: +44 (0)1293 573149 Telefax: +44 (0)1293 573993.