

CFM Metal-Fax Ltd.,  
Unit 2D, Eastlands Ind. Est.,  
Leiston,  
Suffolk. IP16 4LL  
Tel. (0728) 832353/833076

SERVICE BULLETINNO. 9DATE 11.6.90CFM METAL-FAX LTD CONSIDERS

COMPLIANCE - Recommended  
(delete which is not applicable)

SUBJECT SUPPORT FOR FRONT HANGER BRACKET.

MODELS AFFECTED SHADOW SERIES B, B-D, C, C-D,  
STREAK SHADOW SERIES S-A1, S-A

SERIAL NOS. AFFECTED ALL SERIAL NUMBERS

COMPLIANCE TIME NEXT 10 HOUR SERVICE

PURPOSE

TO GIVE SUPPORT TO PLY 'D' SKIN PANELLING BETWEEN HANGER TUBE BRACKETS (FRONT).

INSTRUCTIONS

FIT PLYWOOD PART No. W239 AS A PUSH-FIT BETWEEN HANGER TUBE BRACKETS (PART No. F153). REMOVE AND BOND BACK IN PLACE WITH ARALDITE QUICK-SET EPOXY. (IT IS NOT NECESSARY TO REMOVE PAINT FROM 'D' SKIN BEFORE BONDING, IF THE FIT IS TIGHT).

MATERIAL REQUIRED

W239 - PAD, ARALDITE - QUICK-SET 5 MIN EPOXY.


AVAILABILITY OF PARTS

CFM METAL-FAX.

EFFECTIVITY DATE 11.6.90

SUMMARY

SLIGHT OVER-STRESSING OF THE 'D' BOX PLY SKIN AROUND BRACKETS (F153) IS POSSIBLE IF THE AIRCRAFT IS ABUSED IN THE AIR, e.g. SIDE SLIPPING.

NOTES

COMPLIANCE WITH  
THIS SERVICE  
BULLETIN SHOULD BE  
RECORDED AND  
CERTIFIED IN THE  
AIRCRAFT LOG BOOK.